











#	№ FRITEC	№ ОРИГИНАЛ	АВТОМОБИЛ б	МОДЕЛЬ	РИСУНОК
1	78W33B-MEZ	29108, 29253, 29059, 29061, 29087, 29105, 29106, 29109, 29163, 29179, 29201, 29202, 0980107880, 3057007701, 29278, 1521979, 1734529, 1856108, 1914100, 8285515573, 81508206061, 3057007900, 500054632, 81508206030, 81.50820-6030,, A0064201020, A0044214310	MERCEDES/ MAN/ DAF/ NEOPLAN/ SCANIA	F2000 / TGA / ACTROS/ ACTOROS MP2 AXOR	 <p>247.4 109.5 8122</p> <p>FRITEC 78W33A-F238 F/D/R/T T/E X X 30.0</p> <p>APLICACIONES: BOVA, KASSBOHRER, SCANIA, MERCEDES BENZ</p>
2	78W81A-MEZ	29244, 29245, A0064201520, 0064201520, A0064205320, A9444201102, A9444201202, A9444201302, 9604200102, 9604200202, 9444201002, 9444201102, 9444201202, 9444201302, A0004230316, 0004230316, A0044207583, A0044207683, A0044207783, A0044207883, 0044207583	MERCEDES	ACTROS MP3, MP4,	 <p>207.3 113.9</p> <p>FRITEC 78W81A-Z F417</p>
3	78W82A-MEZ	29246, 29247, A0064201420, 0064201420, A0064205220, 0064205220	MERCEDES	ACTROS MP3, MP4,	 <p>244.2 111.2</p> <p>FRITEC 78W82A-Z F418</p>
4	79W10A-MEZK	29115, 29148, 2918327004145503, 29183, 0980107070, 09.801.07.07.0, MDP3148K, K016382, 031208700130, 81508206054, A0034207220, 0034207220, 55675482, A0044206120	MERCEDES/ MAN	ATEGO/ ATEGO 2/ ATEGO 3/ ANTOS/ TGL	 <p>173.5 84.5</p> <p>FRITEC 78W10A-F135 D/F T/R E/T X X 27.1</p>
5	78W65A-Z	29279, 81508205108, 81508206065, 81508206066, 6403229242, 6403229302, 6403229332, 2927901, 2927931714T3010, JCP075, WP1566, 29223, 1195232, 6402229222, 6402229232	MAN	TGS/ TGX	 <p>217.4 126.9</p> <p>FRITEC 78W65A-F459 D/F T/R E/T X X 30.2</p>
6	78W58A-MEZ	29174, 29218, 29273, 5001864364, 5001864363, 20568711, 21496550, 21024702, 20568714, 21352570, MDP3174K, MDP5104, 7421399929, 7421496555	RENAULT/ VOLVO	MAGNUM DXI/ PREMIUM 2/ FH/ FM	 <p>249.5 109.5 8161</p> <p>FRITEC 78W58A-F306 F/D/R/T T/E X X 29.0</p> <p>APLICACIONES: MERITOR EX225</p>
7	78W49A-ZK	29125, 29277, 20768092, 20918891, 20931343, 209313430, 20932682, 3095396, MDP3125K, MDP3125, 55683981, 16545, 882221	VOLVO	FH/ FL/ FM	 <p>249.2 117.2 8147</p> <p>FRITEC 78W49A-F271 F/D/R/T T/E 78W49A-F271 VOLVO VL220 X X 29.0</p>
8	78W36A-MEZ	29171, 29271, 29158, 29269, 29194, MDP3171K, 3057008501, 3.057.0085.01, 3057008500, 3.057.0085.00, 0980107260, 05.092.90.08.0, 0980106440, 09.801.06.44.0, 0980106950, 09.801.06.95.0, 0980108160, 09.801.08.16.0, 0509290230, 05.092.90.23.0, 0044207020, A0044207020, 1008452, 1005316	BPW		 <p>210.5 108.0 8140</p> <p>FRITEC 78W36A-F269 F/D/R/T T/E X X 29.8</p> <p>APLICACIONES: TEXTAR T3030</p>

#	№ FRITEC	№ ОРИГИНАЛ	АВТОМОБИЛ ь	МОДЕЛЬ	РИСУНОК
9	78W39A-MEZ	29165, 29094, 29197, 29268, MDP3165K, 0980107240, K060273K50, 0509290040, 0509290050, 0509290100, 0980102750, 0980102930, 0980106210, 0980106350, 0980106430	BPW		 <p>8126</p> <p>210.4</p> <p>93.5</p> <p>FRITEC 78W39A-F243 F/D R/T T/E X X 30.0</p> <p>APLICACIONES: BOVA, MAN</p>
10	78W80-MEZ	29228, 09.000.61.79.1, 0900061791, 09.801.07.57.0, 0980107570, 0509290130, 05.092.90.13.0, 1185625, TSB4309, BPW8200, 970025, 2922801, 0980107570, 0580150900, 02.3704.69.00, 0237046900, 0980107971, 05.092.90.16.1, 0509290161, 09.801.07.58.1, 0980107581, 05.801.50.92.0, 0580150920	BPW		
11	78W44A-MEZ	29162, 3057008401, 3057008400, 6402259222, 6402259202, MDP3162, 12999796, 233501309, 1068118, 1101449, 120084, MDP1775, 2916201, 233501309, 151631	SAF		 <p>8159</p> <p>210.7</p> <p>110.0</p> <p>FRITEC 78W44-F293 F/D R/T T/E X X 30.0</p> <p>APLICACIONES:</p>
12	78W93A-ZK	3057009600, 3.057.0096.00, 03057009600, 29175, 29195, 29198, 29274, 29294, 93200, 95396, 1001011780, 95053, 93887, 2917501, SBS2220, 3080008100, 3080008200, GDB5115, 152150, 152150066, D1583- 8795, 152150-066, CVP112K, FCV1814BFE, GDB5101	SAF		